



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Superior Tank Solutions	Type of Inspection:	Scissor lift
Project	Intel - Crystallizer Feed Tank	Date of Inspection	February 26, 2025
Inspector Name	CMagenot@SuperiorTankSolutions.com	Time of Inspection	10:17 AM

NOTES

15 Items Inspected	14 Satisfactory	0 Unsatisfactory	1 N/A
-----------------------	--------------------	---------------------	----------

Scissor lift arrived on site today at 1000.

INSPECTION ITEMS

General

Click "Satisfactory" and enter the model # in the comments section below	Satisfactory
Is the owners manual in place?	Satisfactory
Is the back up alarm or moving alarm working?	Satisfactory
Are the guardrails in place?	Satisfactory
Are the tires in safe condition?	Satisfactory
Is the emergency stop button working?	Satisfactory
Are the indicator lights working?	Satisfactory
Does the platform extension open and close smoothly and lock into place?	Satisfactory

Perform a platform control check. Does everything operate smoothly?

Satisfactory

Perform a ground control check. Does everything operate smoothly?

Satisfactory

Is the lift in overall good condition and the platform clean?

Satisfactory

Are the structure, pins, scissors and covers in good condition?

Satisfactory

Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?

Satisfactory

Does the horn work?

Satisfactory

Check the batteries. Is the water level sufficient?

N/A

