



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Thomas James Homes: NorCal	<b>Type of Inspection:</b>	General Construction
<b>Project</b>	132 Occidental Avenu Burlingame	<b>Date of Inspection</b>	October 08, 2024
<b>Inspector Name</b>	Victor Luva	<b>Time of Inspection</b>	12:33 PM

## NOTES

<b>19</b> Items Inspected	<b>16</b> Satisfactory	<b>0</b> Unsatisfactory	<b>3</b> N/A
------------------------------	---------------------------	----------------------------	-----------------

## INSPECTION ITEMS

### General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Are emergency and labor law postings in place? **Satisfactory**

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **N/A**

Are hand and power tools being used safely? **Satisfactory**

Is good housekeeping being maintained? **Satisfactory**

Is fall protection in place where required? **Satisfactory**

**Is trenching & excavation work being done safely?**

**Satisfactory**

**Are confined space safety procedures being followed?**

**Satisfactory**

**Are scissor lifts / elevated platforms being used safely?**

**N/A**

**Are boom lifts and other aerial devices being used safely?**

**N/A**

**Is heavy equipment being used safely?**

**Satisfactory**

**Are electrical items being used safely?**

**Satisfactory**

**Are roofing operations being performed safely?**

**Satisfactory**

**Is demolition work being done safely?**

**Satisfactory**

**Are all other tasks being performed safely?**

**Satisfactory**

**Any other items?**

**Satisfactory**