

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Trumark Homes: Central Valley	Type of Inspection:	General Construction
Project	Riverstone Arriette 307	Date of Inspection	December 04, 2024
Inspector Name	David (Amador) Ramirez	Time of Inspection	12:56 PM

NOTES					
19	15	0	4		
Items Inspected	Satisfactory	Unsatisfactory	N/A		

INSPECTION ITEMS

INSPECTION ITEMS				
General				
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory			
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory			
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory			
Are emergency and labor law postings in place?	Satisfactory			
Is Personal Protective Equipment being worn as required?	Satisfactory			
Are scaffolding safety procedures being followed?	Satisfactory			
Are hand and power tools being used safely?	Satisfactory			
Is good housekeeping being maintained?	Satisfactory			
Is fall protection in place where required?	Satisfactory			

Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	Satisfactory
Are scissor lifts / elevated platforms being used safely?	Satisfactory
Are boom lifts and other aerial devices being used safely?	Satisfactory
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	N/A