



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Trumark Homes: Central Valley	Type of Inspection:	Framing Inspection
Project	Riverstone Emery 306	Date of Inspection	August 02, 2024
Inspector Name	David (Amador) Ramirez	Time of Inspection	09:17 AM

NOTES

14 Items Inspected	14 Satisfactory	0 Unsatisfactory	0 N/A
------------------------------	---------------------------	----------------------------	-----------------

INSPECTION ITEMS

General

Are air compressors and generators set up safely?	Satisfactory
Are nail guns being used safely?	Satisfactory
Are hole and wall openings protected per OSHA regulations?	Satisfactory
Are stairways in place as required?	Satisfactory
If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly?	Satisfactory
is emergency equipment, including first aid kits and fire extinguishers available?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Is scaffolding set up correctly and being used safely?	Satisfactory
Is fall protection in place where required?	Satisfactory

Is all required PPE being worn including hard hats and eye protection?

Satisfactory

Are electrical cords and other electrical related items in safe condition?

Satisfactory

Are hand and power tools being used safely?

Satisfactory

Is the company safety manual on site?

Satisfactory

Are SDS on site and available to employees?

Satisfactory