

SAFETY INSPECTION REPORT

CONDUCTED FOR:
UC Construction

PROJECT:
Sequoias



INSPECTION TYPE:
General Construction

INSPECTOR : FRANCISCO ROMERO
DATE : SEPTEMBER 17, 2024
CITY : CORCORAN
STATE : CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	24 Satisfactory	1 Unsatisfactory	28 N/A
------------------------------	---------------------------	----------------------------	------------------

At my arrival to the site , I met the superintendent Jose Gonzalez and we went to Hines trailer for paperwork inspection. During the inspection I verified:

Labor posters, fire extinguisher, emergency locations , first aid kit was missing on site, Mr. Gonzalez will take care of it today. Everything looked good.

While I was there, we did a safety meeting, topics covered were : impalement hazards and valley fever.

Subs on site

Quadrant Concrete. No violations were found on site

I will provide report for their review.

INSPECTION ITEMS

Documentation

Site Contact **Satisfactory**

Safety Program (Including IIPP) **N/A**

Comment

Safety binder will be verified on my next visit,,, I failed to ask about it.

-

Heat Illness Prevention Program **Satisfactory**

Safety Data Sheets **Satisfactory**

Daily Inspections **Satisfactory**

Tailgate Meetings **Satisfactory**

Sub-Contractor Meetings **Satisfactory**

OSHA Permits **Satisfactory**

Labor Law Postings **Satisfactory**

Comment	
I verified labor poster in the site trailer	

Emergency / Other Postings **Satisfactory**

Comment	
Emergency locations were verified	

First Aid / CPR Certification **N/A**

Emergency Items

Access / Egress **N/A**

Elevator for Hoisting Workers (if needed) **N/A**

Fire Extinguisher(s) **Satisfactory**

Comment

Fire extinguisher was verified in the site trailer



First Aid Kit(s)

Unsatisfactory

Comment

First aid kit was missing on site. Mr. Gonzalez will get one promptly

-

Eye Wash Station

Satisfactory

Other Fire Fighting Equipment (If needed)

N/A

General Items

Restrooms

Satisfactory

Hand Washing Stations

Satisfactory

Waste Containers

Satisfactory

Potable Water

Satisfactory

Shade

Satisfactory

Tools & Equipment

Power Tools

Satisfactory

Hand Tools


Satisfactory

Powder Actuated Tools

N/A

Pneumatic Nailers	N/A
Mobile Elevated Work Platforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	N/A

Operations

Personal Protective Equipment	Satisfactory
Comment	
Workers were wearing all their gear on site	

Trenching & Excavation	Satisfactory
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A

Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Comment	
Metal stakes had their caps for traffic safety.	-
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	N/A
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A