

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
UC Construction

**PROJECT:**  
Sequoias



**INSPECTION TYPE:**  
General Construction

**INSPECTOR:** FRANCISCO ROMERO  
**DATE:** JANUARY 24, 2025  
**CITY:** CORCORAN  
**STATE:** CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>28</b> Satisfactory	<b>0</b> Unsatisfactory	<b>25</b> N/A
------------------------------	---------------------------	----------------------------	------------------

At my arrival to the site , I met the superintendent Jose Gonzalez and we went to trailer for paperwork inspection. During the inspection I verified:

Labor posters , fire extinguisher , first aid kit was available in the site trailer. Everything looked good.

While I was there, we did a safety meeting, topics covered were : PPE AND NEAR MISSES .

Subs on site

- Tri valley drywall
- Garcia Electric
- Quadrant Concrete

During the inspection, I found No violations on site.

Mr. Gonzalez does a great job enforcing safety.

I will provide report for their review.

# INSPECTION ITEMS

## Documentation

<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	<b>UC CONSTRUCTION</b>
During the inspection, I met Mr. Gonzalez on site and we did the inspection together.	-

<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Comment</b>	-

Safety Program is available	-
-----------------------------	---

<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Comment</b>	-
Heat Illness Prevention Program is available and site specific information is completed.	-

<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Comment</b>	-
SDS are available for employee access	-

<b>Daily Inspections</b>	<b>Satisfactory</b>
<b>Comment</b>	-
Daily inspections are being performed	-


<b>Tailgate Meetings</b>	<b>Satisfactory</b>
<b>Comment</b>	-
Tailgates are being conducted at least every 10 working days	-

<b>Sub-Contractor Meetings</b>	<b>Satisfactory</b>
<b>Comment</b>	-
Sub contractors are performing their tailgate meetings at least every 10 working days	-

<b>OSHA Permits</b>	<b>Satisfactory</b>
<b>Comment</b>	-
Required Cal/OSHA permits have been pulled and are posted	-

<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	-

I verified labor poster in the site trailer




**Emergency / Other Postings**

**Satisfactory**

**Comment**

Emergency locations were verified



**First Aid / CPR Certification**

**N/A**

**Emergency Items**

**Access / Egress**

**N/A**

**Elevator for Hoisting Workers (if needed)**

**N/A**

**Fire Extinguisher(s)**

**Satisfactory**

**Comment**

Fire extinguisher was verified in the site trailer



<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
First aid was verified on site	-

<b>Eye Wash Station</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
Eye wash on site and is current	-

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

<b>General Items</b>	
----------------------	--

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Comment</b>	
Plenty of toilets are located on site and are being kept clean and in good working order.	-

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Comment</b>	
Wash stations are clean and in sanitary condition. There is an adequate supply of soap and paper towels.	-

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
Waste containers provided	-

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Shade</b>	<b>Satisfactory</b>
<b>Comment</b>	
Shade on site and suitable	-

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
<b>Comment</b>	
All power tools and equipment in good functional order	-

<b>Hand Tools</b>	<b>Satisfactory</b>
<b>Comment</b>	
Powers tools are UL approved	-

<b>Powder Actuated Tools</b>	<b>N/A</b>
------------------------------	------------

<b>Pneumatic Nailers</b>	<b>N/A</b>
--------------------------	------------

<b>Mobile Elevated Work Plarforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>N/A</b>
----------------------------------	------------

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
--	------------

<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>Satisfactory</b>
----------------	---------------------

## Operations

<b>Personal Protective Equipment</b>	<b>Satisfactory</b>
<b>Comment</b>	<b>Quadrant Concrete</b>


All PPE being worn



**Comment**

**Tri Valley**

All PPE being worn



**Comment**

**Quadrant Concrete**

All PPE being worn



**Trenching & Excavation**

**Satisfactory**

**Comment**

Permits as well as notification on site for excavation



<b>Fall Protection</b>	<b>N/A</b>
<b>Guardrails</b>	<b>N/A</b>
<b>Floor / Wall Openings</b>	<b>N/A</b>
<b>Supported Scaffolding</b>	<b>N/A</b>
<b>Mobile Scaffolding</b>	<b>N/A</b>
<b>Suspended Scaffolding</b>	<b>N/A</b>
<b>Confined Spaces</b>	<b>N/A</b>
<b>Impalement Hazards</b>	<b>Satisfactory</b>
<b>Traffic Control</b>	<b>Satisfactory</b>
<b>Roofing Operations</b>	<b>N/A</b>
<b>Housekeeping</b>	<b>Satisfactory</b>
<b>Comment</b>	
Housekeeping in good shape.	-
<b>Demolition</b>	<b>N/A</b>
<b>Silica Control</b>	<b>Satisfactory</b>
<b>Rigging Operations</b>	<b>N/A</b>
<b>Hot Work</b>	<b>N/A</b>
<b>Electrical Safety</b>	<b>Satisfactory</b>



<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Stairways, Ramps, Runways</b>	<b>N/A</b>
<b>Other Items (that were observed)</b>	<b>N/A</b>