

SAFETY INSPECTION REPORT

CONDUCTED FOR:
UC Construction

PROJECT:
South Point 10



INSPECTION TYPE:
General Construction

INSPECTOR : FRANCISCO ROMERO
DATE : DECEMBER 05, 2024
CITY : LOS BANOS
STATE : CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	26 Satisfactory	2 Unsatisfactory	25 N/A
------------------------------	---------------------------	----------------------------	------------------

At my arrival, I met the new superintendent on site. Cole Wristen and we did the inspection together..

During the inspection, these were the subs on site.

- I F Plaster
- APP PLUMBING
- BLUE MOUNTAIN
- BC Electric
- MCR Painting

During the inspection, I found a couple hard hat violations which they were corrected on the spot.

- MCR Painting: Found a few workers not wearing hard hats
- BC Electric :found worker not using the ladder safely
- IF Plasterer. Was leaning the ladder against the wall

These violations were corrected on site.

I will forward report for their review.

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
Comment	
Met Cole on site and we did the safety meeting and we did the inspection together	-

Safety Program (Including IIPP)

Satisfactory

Comment	
Safety Program is available	-

Heat Illness Prevention Program

Satisfactory

Comment	
Heat Illness Prevention Program is available and site specific information is completed.	-

Safety Data Sheets	Satisfactory
Comment	
SDS are available for employee access	-

Daily Inspections	Satisfactory
Comment	
Daily inspections are being performed	-

Tailgate Meetings	Satisfactory
--------------------------	---------------------

Sub-Contractor Meetings	Satisfactory
--------------------------------	---------------------

OSHA Permits	Satisfactory
Comment	
Required Cal/OSHA permits have been pulled and are posted	-

Labor Law Postings	Satisfactory
Comment	
Labor law postings are in place as required.	-

Emergency / Other Postings	Satisfactory
Comment	
Emergency posters are on site and directions to nearest medical facility are posted.	-

First Aid / CPR Certification	Satisfactory
--------------------------------------	---------------------

Emergency Items

Access / Egress	Satisfactory
Comment	

Availability of emergency medical service for workers on site	-
---	---

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Satisfactory
-----------------------------	---------------------

Comment	
----------------	--

ABC fire extinguisher inspected once a month and once a year by a company	-
---	---

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Comment	
----------------	--

First aid kits are available	-
------------------------------	---

Eye Wash Station	Satisfactory
-------------------------	---------------------

Comment	
----------------	--

Eye wash on site and is current	-
---------------------------------	---

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
------------------	---------------------

Comment	
----------------	--

Plenty of toilets are located on site and are being kept clean and in good working order.	-
---	---

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Comment	
----------------	--

Wash stations are clean and in sanitary condition. There is an adequate supply of soap and paper towels.	-
--	---

Waste Containers	Satisfactory
-------------------------	---------------------

Comment	
----------------	--

Waste containers provided	-
---------------------------	---

Potable Water	Satisfactory
----------------------	---------------------

Comment	
Provide clean	-

Shade	Satisfactory
Comment	
Shade on site and suitable	-

Tools & Equipment

Power Tools	Satisfactory
Comment	
All power tools and equipment in good functional order	-

Hand Tools	Satisfactory
Comment	
Powers tools are UL approved	-

Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Platforms (MEWP's)	N/A
--	------------



Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
--	------------

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	Unsatisfactory
Comment	

<p>Found trade almost on top of a frame ladder. Bc electric</p>	
<p>Found another worker leaning the ladder against the wall.</p>	

Operations

Personal Protective Equipment **Unsatisfactory**

Comment

Flooring company were not wearing hard hats -

MCR painting workers were not wearing hard hats on site



Trenching & Excavation **N/A**

Fall Protection **N/A**

Guardrails **N/A**

Floor / Wall Openings **N/A**

Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	N/A
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Comment	
Housekeeping in good shape.	-
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	Satisfactory
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A