

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
UC Construction

**PROJECT:**  
Stoneridge



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** ESPITIA GUS  
**DATE :** DECEMBER 11, 2024  
**CITY :** MERCED  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>54</b> Items Inspected	<b>13</b> Satisfactory	<b>2</b> Unsatisfactory	<b>39</b> N/A
------------------------------	---------------------------	----------------------------	------------------

Upon my arrival, I went to the construction trailer to look for Gorge, but the trailer was locked, and I did not see him on-site.

As I walked the job site, I observed only two trades working: Blue Mountain was checking the pressure on pipes, and California Building Products was installing interior insulation.

Overall, the site maintained good housekeeping practices, and the restrooms were clean and well-maintained.

## INSPECTION ITEMS

### Documentation

<b>Site Contact</b>	<b>N/A</b>
<b>Comment</b>	
I did not see the superintendent around, but I went ahead and conducted the inspection	-

<b>Safety Program (Including IIPP)</b>	<b>N/A</b>
<b>Comment</b>	
Superintendent was not around and the construction trailer was lock so I couldn't verify	-

<b>Heat Illness Prevention Program</b>	<b>N/A</b>
<b>Comment</b>	
Superintendent was not around and the construction trailer was lock so I couldn't verify	-

<b>Safety Data Sheets</b>	<b>N/A</b>
<b>Comment</b>	
Superintendent was not around and the construction trailer was locked so I couldn't verify	-

<b>Daily Inspections</b>		<b>N/A</b>
<b>Comment</b>		
The superintendent was not at the job site so I was not able to verify		-

<b>Tailgate Meetings</b>		<b>N/A</b>
<b>Comment</b>		
The superintendent was not at the job site so I was not able to verify		-

<b>Sub-Contractor Meetings</b>		<b>N/A</b>
--------------------------------	--	------------

<b>OSHA Permits</b>		<b>N/A</b>
<b>Comment</b>		
The superintendent was not around and the construction trailer was locked so I couldn't verify		-

<b>Labor Law Postings</b>		<b>N/A</b>
<b>Comment</b>		
The superintendent was not around and the construction trailer was locked so I couldn't verify		-

<b>Emergency / Other Postings</b>		<b>N/A</b>
<b>Comment</b>		
The superintendent was not around and the construction trailer was locked so I couldn't verify		-

<b>First Aid / CPR Certification</b>		<b>N/A</b>
<b>Comment</b>		
The superintendent was not at the job site so was not able to verify		-

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>		<b>N/A</b>
<b>Comment</b>		
The superintendent was not around and the construction trailer was locked so I couldn't verify		-

<b>First Aid Kit(s)</b>		<b>N/A</b>
<b>Comment</b>		
The superintendent was not around and the construction trailer was locked so I couldn't verify		-

<b>Eye Wash Station</b>		<b>N/A</b>
<b>Comment</b>		
The superintendent was not around and the construction trailer was locked so I couldn't verify		-

<b>Personnel Hoist</b>		<b>N/A</b>
------------------------	--	------------

<b>Other Fire Fighting Equipment (If needed)</b>		<b>N/A</b>
--	--	------------

## General Items

<b>Restrooms</b>		<b>Satisfactory</b>
<b>Comment</b>		
Plenty of toilets are located on site and are being kept clean and in good working order.		-

<b>Hand Washing Stations</b>		<b>Satisfactory</b>
<b>Comment</b>		
Wash stations are clean and in sanitary condition. There is an adequate supply of soap and paper towels.		-

<b>Waste Containers</b>		<b>Satisfactory</b>
<b>Comment</b>		
The superintendent was not at the job site so was not able to verify		-

<b>Potable Water</b>		<b>Satisfactory</b>
----------------------	--	---------------------

**Comment**

Drinking water is available on-site



**Shade**

**Satisfactory**

**Comment**

Structural shade is available on-site

-

**Tools & Equipment**

**Power Tools**

**Satisfactory**

**Hand Tools**

**Satisfactory**

**Powder Actuated Tools**

**N/A**

**Pneumatic Nailers**

**N/A**

**Mobile Elevated Work Platforms (MEWP's)**

**N/A**

**Powered Industrial Trucks**

**N/A**

**Heavy Mobile Equipment (Excavators, Loaders, etc)**

**N/A**

**Cranes**

**N/A**

**Cylinder Storage**

**N/A**

**Ladders**

**Unsatisfactory**

**Comment**

California Building Product worker was standing on top of the ladder



## Operations

### Personal Protective Equipment

Satisfactory

#### Comment

All PPE being worn

-

### Trenching & Excavation

N/A

#### Comment

No open trenches on-site

-

### Fall Protection

N/A

#### Comment

Nobody was working above trigger heights that required the use of fall protection during the inspection

-

### Guardrails

N/A

### Floor / Wall Openings

N/A

### Supported Scaffolding

Satisfactory

#### Comment

The scaffolding structure seems to be well-erected, it has all the required safety components in place



<b>Mobile Scaffolding</b>	<b>N/A</b>
---------------------------	------------

<b>Suspended Scaffolding</b>	<b>N/A</b>
------------------------------	------------

<b>Confined Spaces</b>	<b>N/A</b>
------------------------	------------

<b>Impalement Hazards</b>	<b>Satisfactory</b>
---------------------------	---------------------

<b>Comment</b>	
----------------	--

No impalement hazards were observed during the safety inspection	-
--	---

<b>Traffic Control</b>	<b>N/A</b>
------------------------	------------

<b>Roofing Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Comment</b>	
----------------	--

No roofing operation during the safety inspection	-
---	---

<b>Housekeeping</b>	<b>Satisfactory</b>
---------------------	---------------------

<b>Comment</b>	
----------------	--

Good housekeeping	-
-------------------	---

<b>Demolition</b>	<b>N/A</b>
-------------------	------------

<b>Silica Control</b>	<b>N/A</b>
-----------------------	------------

<b>Rigging Operations</b>	<b>N/A</b>
---------------------------	------------


<b>Hot Work</b>	<b>N/A</b>
-----------------	------------

<b>Electrical Safety</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Comment</b>	
The building is not energized and the power cords are in good conditions	-

<b>Lockout / Tagout</b>	<b>N/A</b>
-------------------------	------------

<b>Stairways, Ramps, Runways</b>	<b>Unsatisfactory</b>
----------------------------------	-----------------------

<b>Comment</b>	
The stairway is missing handrails	

<b>Other Items (that were observed)</b>	<b>N/A</b>
---	------------