

SAFETY INSPECTION REPORT

CONDUCTED FOR:
West Builders, Inc.

PROJECT:
Fullerton HUB



INSPECTION TYPE:
General Construction

INSPECTOR : JUSTYN BLANCHARD
DATE : JANUARY 06, 2025
CITY : FULLERTON
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	33 Satisfactory	2 Unsatisfactory	18 N/A
------------------------------	---------------------------	----------------------------	------------------

The site was visited for a safety inspection. The contractors on site were observed regarding items including PPE, tools, and equipment and safe practices. Items of concern are noted in this report. The observations were discussed with the project team.

Contractors Onsite:

- Tinco
- Trademark
- Rye
- AmPam
- Lighthouse Glass
- Sharpe
- Atlas
- Hiller Fire
- Bali
- Brix
- New Generation Granite
- Patterson

Site Specific Activity:

Note, all trades accessing the scaffold must have a daily inspection of the scaffold. The competent person must make any corrections prior to work commencing.

Trades are engaged in rough in of plumbing and electrical. Wood and metal framing activities are in process.

Window installation and work from scaffolding.

See observations of the site below.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory

Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	Unsatisfactory
Fire Extinguisher(s)	Satisfactory
First Aid Kit(s)	Satisfactory
Eye Wash Station	N/A
Other Fire Fighting Equipment (If needed)	Satisfactory

General Items

Restrooms

Satisfactory

Hand Washing Stations

Satisfactory

Waste Containers

Satisfactory

Potable Water

Satisfactory

Shade

Satisfactory

Tools & Equipment

Power Tools

Satisfactory

Hand Tools

Satisfactory

Powder Actuated Tools

N/A

Pneumatic Nailers

N/A

Mobile Elevated Work Platforms (MEWP's)

N/A

Powered Industrial Trucks

N/A

Heavy Mobile Equipment (Excavators, Loaders, etc)

N/A

Cranes

N/A

Cylinder Storage

Satisfactory

Ladders

Unsatisfactory

Operations

Personal Protective Equipment	Satisfactory
Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	Satisfactory
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	Satisfactory
Electrical Safety	Satisfactory

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	Satisfactory
----------------------------------	---------------------

Other Items (that were observed)	N/A
---	------------