SAFETY INSPECTION REPORT

CONDUCTED FOR:

W.L. Butler Construction, Inc.

PROJECT:
TARGET FRESNO 205



INSPECTION TYPE:General Construction

INSPECTOR: KIM BURGESS DATE: FEBRUARY 25, 2025

CITY: CLOVIS STATE: CA

SITE CONTACT: JOSE

ADDITIONAL SITE CONTACT: N/A

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION 52 Items Inspected 36 Satisfactory 2 Unsatisfactory N/A

Completed a site inspected February 25, 2025.

Walked site with Jose.

Here are findings from today's inspection.

W.L. Butler-Upon arrival checked in at job trailer. Trailer had required labor law postings. IIPP on site. Heat illness program set with water replenishment forms. Emergency site plan on site. Restrooms are serviced 2 times a week.

- -Need Code of Safe Practices posted in trailer.
- -Need to document monthly inspections of fire extinguishers.

These items were corrected on site.

SUBS ON SITE:

- *CALIFORNIA BUILDING PRODUCTS
- *CHM
- *PDCI
- *BERGER STEEL
- *PAUL DURHAM ELECTRIC
- *SUPERIOR WALL SYSTEMS
- *AMS
- *GLAZING CONCEPTS

NOTE: All violations were corrected on site. See report for details of inspection.

INSPECTION ITEMS

Documentation

Safety Program (Including IIPP)

Satisfactory

Comment	W.L. Butler
Safety Program is available	-

Heat Illness Prevention Program Comment W.L. Butler Heat Illness Prevention Program is available and site specific information is completed.

Safety Data Sheets	Satisfactory
Comment	W.L. Butler
SDS are available for employee access	-

Daily Inspections	Satisfactory
Comment	W.L. Butler
Daily inspections are being performed	-

Tailgate Meetings	Satisfactory
Comment	W.L. Butler
Tailgates are being conducted at least every 10 working days	Machine State of Machin

Sub-Contractor Meetings Satisfactory

OSHA Permits Satisfactory

Comment

W.L. Butler

OSHA 300 log posted.



Labor Law Postings Comment W.L. Butler Labor law postings are in place as required. -

Emergency / Other Postings

Satisfactory

Comment

W.L. Butler

Emergency posters are on site and directions to nearest medical facility are posted.



Comment

Emergency site plan present in trailer for employee access.



First Aid / CPR Certification

Satisfactory

Comment	-
Compliant	-

Emergency Items

Access / Egress Satisfactory

Elevator for Hoisting Workers (if needed)

N/A

Fire Extinguisher(s)	Satisfactory
Comment	W.L. Butler
Observed not signing inspection on a monthly basis. Was corrected on site.	-

First Aid Kit(s)	Satisfactory
Comment	W.L. Butler
Compliant	-

Comment PLS PLS has eyewash station on site and being inspected monthly.

Other Fire Fighting Equipment (If needed)

N/A

General Items	
Restrooms	Satisfactory
Comment	-
Plenty of toilets are located on site and are being kept clean and in good working order.	-

Hand Washing Stations	Satisfactory
Comment	-
Wash stations are clean and in sanitary condition. There is an adequate supply of soap and paper towels.	-

Waste Containers	Satisfactory
Comment	-
Waste containers provided	-

Potable Water	Satisfactory
Comment	W.L. Butler
Water replenishment in place.	-

Shade	Satisfactory
Comment	-
Compliant.	-

Power Tools Comment Superior Wall Systems Need back board when cutting material. Was corrected on site.

Hand Tools	Satisfactory
Comment	-
Powers tools are UL approved	-

Personal Protective Equipment

Comment

Satisfactory

Powder Actuated Tools	Satisfactory
Comment	Superior Wall Systems
Powder actuated strips were found on site. Violation was corrected on site.	-
Pneumatic Nailers	Satisfactory
Comment	-
Nail guns are being disconnected from compressed air when not in use	-
Mobile Elevated Work Plarforms (MEWP's)	Unsatisfactory
Comment	California Building Products.
Guard chain not in place on elevated platform. Was corrected on site.	-
Powered Industrial Trucks	Satisfactory
Comment	-
Operators are certified	-
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	Satisfactory
Comment	•
Cylinders are secured	-
Ladders	Satisfactory
Comment	
Ladders were found to be in good condition and are being inspected daily	-
Operations	

All PPE being worn	-
Trenching & Excavation	Satisfactory
Fall Protection	Satisfactory
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	Satisfactory
Comment	Glazing Concepts
Scaffolding had green inspection tags in place. Inspected daily	-
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Comment	Paul Durham Electric
Protective covers designed to cover exposed reinforced steel and other similar projections so as to prevent impalement	
Traffic Control	N/A
Roofing Operations	N/A

Housekeeping	Satisfactory
Comment	-
Housekeeping in good shape.	-

Demolition N/A

Silica Control Comment PDCI Silica dust being controlled by water.

Rigging Operations N/A

Hot Work Comment Superior Wall Systems A hot work permit is filled out. Fire extinguisher present.

Electrical Safety	Satisfactory
Comment	-
Electrical items safe.	-

Lockout / Tagout Satisfactory

Stairways, Ramps, Runways

Satisfactory

Comment

Temporary stairs in place



Other Items (that were observed)

N/A