

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Woodside Homes: Arizona

PROJECT:
Enchantment



INSPECTION TYPE:
General Construction

INSPECTOR : SEAN NELSON

DATE : JULY 25, 2024

CITY :

STATE :

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	26 Satisfactory	4 Unsatisfactory	23 N/A
------------------------------	---------------------------	----------------------------	------------------

The safety checklist was posted, it has not been filled out since January.

The fire extinguisher inside of the safety center hasn't been inspected since January.

We found a few issues with the scaffolding on site.

INSPECTION ITEMS

Documentation

Site Contact **Satisfactory**

Safety Program (Including IIPP) **Satisfactory**


Heat Illness Prevention Program **Satisfactory**

Safety Data Sheets **Satisfactory**

Daily Inspections **Unsatisfactory**

Comment

The safety checklist hasn't been filled out since January.



Tailgate Meetings **Satisfactory**

Sub-Contractor Meetings	Satisfactory
--------------------------------	---------------------

OSHA Permits	Satisfactory
---------------------	---------------------

Labor Law Postings	Satisfactory
---------------------------	---------------------

Emergency / Other Postings	Satisfactory
-----------------------------------	---------------------


First Aid / CPR Certification	Satisfactory
--------------------------------------	---------------------

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Unsatisfactory
-----------------------------	-----------------------

Comment	
The fire extinguisher inside of the safety center hasn't been inspected since January.	

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Eye Wash Station	Satisfactory
-------------------------	---------------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
------------------	---------------------

Hand Washing Stations	Unsatisfactory
Comment	
No hand washing station has yet been setup for this job site	-

Waste Containers	Satisfactory
-------------------------	---------------------

Potable Water	Satisfactory
----------------------	---------------------

Shade	Satisfactory
--------------	---------------------

Tools & Equipment

Power Tools	Satisfactory
--------------------	---------------------

Hand Tools	Satisfactory
-------------------	---------------------

Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Platforms (MEWP's)	N/A
--	------------

Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
--	------------

Cranes	N/A
---------------	------------



Cylinder Storage	N/A
-------------------------	------------


Ladders	Satisfactory
----------------	---------------------

Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------

Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A

Suspended Scaffolding	Unsatisfactory
Comment	
<p>This section of scaffolding was green tagged but was missing, guardrails and end rails and wasn't fully planked.</p>	
<p>All sections of scaffolding need end rails and ladder access is also required.</p>	

<p>We'd to make sure that bad planks are not used for the scaffold platform.</p>	
--	---

<p>Confined Spaces</p>	<p>N/A</p>
<p>Impalement Hazards</p>	<p>N/A</p>
<p>Traffic Control</p>	<p>Satisfactory</p>
<p>Roofing Operations</p>	<p>N/A</p>
<p>Housekeeping</p>	<p>Satisfactory</p>
<p>Demolition</p>	<p>N/A</p>
<p>Silica Control</p>	<p>Satisfactory</p>
<p>Rigging Operations</p>	<p>N/A</p>
<p>Hot Work</p>	<p>N/A</p>
<p>Electrical Safety</p>	<p>Satisfactory</p>
<p>Lockout / Tagout</p>	<p>N/A</p>
<p>Stairways, Ramps, Runways</p>	<p>Satisfactory</p>
<p>Other Items (that were observed)</p>	<p>N/A</p>