SAFETY INSPECTION REPORT

CONDUCTED FOR: Woodside Homes: Arizona

PROJECT:

Horizon at the Dells



INSPECTION TYPE: General Construction

INSPECTOR : SEAN NELSON DATE : MAY 29, 2024 CITY : STATE :

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
52	28	5	19
Items Inspected	Satisfactory	Unsatisfactory	N/A

Need to make sure that the scaffolding is inspected before use. Need to make sure that all trades on site wear their personal protective equipment. The safety checklist was posted, it has not been filled out since January.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Sefety Preasen (Including IIDD)	Catiofactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Unsatisfactory

Comment

The safety checklist was posted, but hasn't been filled out in months.

First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	Satisfactory
Fire Extinguisher(s)	Unsatisfactory
Comment	
The fire extinguisher inside of the safety center hasn't been inspected since January.	
First Aid Kit(s)	Satisfactory
Eye Wash Station	Satisfactory
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Unsatisfactory
Comment Page 3 of 7	

No hand washing station has yet been setup for this job site	-
Waste Contatiners	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
Tools & Equipment	
Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	Satisfactory
Ladders	Satisfactory
Operations	
Personal Protective Equipment	Unsatisfactory

Comment

There were a couple of workers on site not wearing their hard hats.	
]

Trenching & Excavation	Satisfactory
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A

Suspended Scaffolding	Unsatisfactory
Comment	
Need to make sure that there are no gaps greater than an inch in between planks.	

Need to make sure that all sections of scaffolding are fully planked.	
Need to make sure that baseplates and mud-sills are kept visible for inspection.	
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A

Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A