



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Woodside Homes: Arizona	Type of Inspection:	General Construction
Project	Horizon at the Dells	Date of Inspection	July 02, 2024
Inspector Name	Nate Wools	Time of Inspection	03:54 PM

NOTES

19 Items Inspected	13 Satisfactory	0 Unsatisfactory	6 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Are emergency and labor law postings in place? **Satisfactory**

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **N/A**

Are hand and power tools being used safely? **Satisfactory**

Is good housekeeping being maintained? **Satisfactory**

Is fall protection in place where required? **N/A**

Is trenching & excavation work being done safely?

Satisfactory

Are confined space safety procedures being followed?

Satisfactory

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

Satisfactory

Are electrical items being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Any other items?

Satisfactory