

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Woodside Homes: Arizona

**PROJECT:**  
Icon at Thunderbird



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** SEAN NELSON  
**DATE :** MAY 30, 2024  
**CITY :**  
**STATE :**

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>52</b> Items Inspected	<b>31</b> Satisfactory	<b>4</b> Unsatisfactory	<b>17</b> N/A
------------------------------	---------------------------	----------------------------	------------------


The safety checklist was posted, it has yet been filled out for May. The fire extinguisher has not yet been signed off for May. There were multiple issues with the scaffolding on site.

# INSPECTION ITEMS

## Documentation

<b>Site Contact</b>	<b>Satisfactory</b>
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Safety Data Sheets</b>	<b>Satisfactory</b>

## Daily Inspections Unsatisfactory

Comment	
Safety checklist has been posted, but hasn't been filled out for May.	

## Tailgate Meetings Satisfactory


## Sub-Contractor Meetings Satisfactory

OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory

**Emergency Items**

Access / Egress	Satisfactory
-----------------	--------------

Fire Extinguisher(s)	Unsatisfactory
----------------------	----------------

Comment	
The fire extinguisher wasn't inspected in May.	

First Aid Kit(s)	Satisfactory
------------------	--------------

Eye Wash Station	Satisfactory
------------------	--------------

Other Fire Fighting Equipment (If needed)	N/A
---	-----

**General Items**

Restrooms	Satisfactory
-----------	--------------

Hand Washing Stations	Unsatisfactory
-----------------------	----------------

Comment	
No hand washing station has yet been setup for this job site	-

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Shade</b>	<b>Satisfactory</b>
--------------	---------------------

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
--------------------	---------------------

<b>Hand Tools</b>	<b>Satisfactory</b>
-------------------	---------------------

<b>Powder Actuated Tools</b>	<b>N/A</b>
------------------------------	------------

<b>Pneumatic Nailers</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>N/A</b>
----------------------------------	------------

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
--	------------

<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>Satisfactory</b>
----------------	---------------------

### Comment

Workers were doing a great job with ladder safety.



## Operations

Personal Protective Equipment

Satisfactory

Trenching & Excavation

N/A

Fall Protection

Satisfactory

Guardrails

Satisfactory

Floor / Wall Openings

N/A

Supported Scaffolding

N/A

Mobile Scaffolding

N/A

Suspended Scaffolding

Unsatisfactory


### Comment

Need to make sure level plumb rails are used for scaffolding. Need to replace bent members.



Need to make sure that all sections of scaffolding have been tagged.



<p>Need to keep baseplates and mud-sills visible for inspection.</p>	
--	---

<p><b>Confined Spaces</b></p>	<p><b>N/A</b></p>
-------------------------------	-------------------

<p><b>Impalement Hazards</b></p>	<p><b>Satisfactory</b></p>
----------------------------------	----------------------------

<p><b>Traffic Control</b></p>	<p><b>Satisfactory</b></p>
-------------------------------	----------------------------

<p><b>Roofing Operations</b></p>	<p><b>Satisfactory</b></p>
----------------------------------	----------------------------

<p><b>Housekeeping</b></p>	<p><b>Satisfactory</b></p>
----------------------------	----------------------------

<p><b>Demolition</b></p>	<p><b>N/A</b></p>
--------------------------	-------------------

<p><b>Silica Control</b></p>	<p><b>Satisfactory</b></p>
------------------------------	----------------------------

<p><b>Rigging Operations</b></p>	<p><b>N/A</b></p>
----------------------------------	-------------------

<p><b>Hot Work</b></p>	<p><b>N/A</b></p>
------------------------	-------------------

<p><b>Electrical Safety</b></p>	<p><b>Satisfactory</b></p>
---------------------------------	----------------------------

<p><b>Lockout / Tagout</b></p>	<p><b>N/A</b></p>
--------------------------------	-------------------

<p><b>Stairways, Ramps, Runways</b></p>	<p><b>Satisfactory</b></p>
---	----------------------------

<p><b>Other Items (that were observed)</b></p>	<p><b>N/A</b></p>
--	-------------------