



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Woodside Homes: Arizona	Type of Inspection:	Log a Safety Observation
Project	Icon at Thunderbird	Date of Inspection	June 27, 2024
Inspector Name	Lina Sanchez	Time of Inspection	02:12 PM

NOTES

7 Items Inspected	6 Satisfactory	1 Unsatisfactory	0 N/A
----------------------	-------------------	---------------------	----------

INSPECTION ITEMS

General

Ladder Safety - Log a Safety Observation	Satisfactory
Fall Protection - Log a Safety Observation	Satisfactory
Scaffolding - Log a Safety Observation	Satisfactory
Equipment - Log a Safety Observation	Satisfactory
COVID Protocols / Social Distancing - Log a Safety Observation	Satisfactory
PPE/Hard Hats - Log a Safety Observation	Unsatisfactory
Comment	
64 electrician no hard hat	-
OTHER - Click Satisfactory to log a good safety observation, or click unsatisfactory to log a negative safety observation.	Satisfactory