

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Woodside Homes: Arizona

PROJECT:
Ironwood Village at North Creek



INSPECTION TYPE:
General Construction

INSPECTOR : SEAN NELSON
DATE : JUNE 25, 2024
CITY :
STATE :

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	26 Satisfactory	3 Unsatisfactory	24 N/A
------------------------------	---------------------------	----------------------------	------------------

Unable to gain access to the safety center, site superintendent was not available at the time of inspection.

Need to stay on top of housekeeping, several boards with nails protruding out of them.

Had to speak to the framers about using folded A-frame ladders.

Everyone did a great job with wearing their personal protective equipment.

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	N/A
Comment	
Wasn't able to verify the safety checklist, the safety center was locked.	-
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory

Labor Law Postings	Satisfactory
--------------------	--------------

Emergency / Other Postings	Satisfactory
----------------------------	--------------

First Aid / CPR Certification	Satisfactory
-------------------------------	--------------

Emergency Items

Access / Egress	Satisfactory
-----------------	--------------

Elevator for Hoisting Workers (if needed)	N/A
---	-----

Fire Extinguisher(s)	Satisfactory
----------------------	--------------

First Aid Kit(s)	Satisfactory
------------------	--------------

Eye Wash Station	Satisfactory
------------------	--------------

Other Fire Fighting Equipment (If needed)	N/A
---	-----

General Items

Restrooms	Satisfactory
-----------	--------------

Hand Washing Stations	Unsatisfactory
-----------------------	----------------

Comment	
---------	--

No hand washing station has yet been setup for this job site	-
--	---

Waste Containers	Satisfactory
------------------	--------------



Potable Water	Satisfactory
---------------	--------------

Shade	Satisfactory
-------	--------------

Tools & Equipment

Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Platforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A

Ladders	Unsatisfactory
----------------	-----------------------

Comment	
<p>The framers had a couple of safety issues with using ladders on site, like using an A-frame ladder.</p>	
<p>Ladders used for access must be tied off and extend three feet over the leading edge.</p>	

Operations

Personal Protective Equipment

Satisfactory

Comment

Everyone was doing a good job with wearing their personal protective equipment.



Trenching & Excavation

Satisfactory

Fall Protection

Satisfactory

Comment

The framers were doing a good job with wearing their harnesses and being tied off.



Guardrails

N/A

Floor / Wall Openings

N/A

Supported Scaffolding

N/A

Mobile Scaffolding

N/A


Suspended Scaffolding

N/A

Confined Spaces

N/A


Impalement Hazards	Satisfactory
---------------------------	---------------------

Comment	
All impalement hazards were secured.	

Traffic Control	Satisfactory
------------------------	---------------------

Roofing Operations	N/A
---------------------------	------------

Housekeeping	Unsatisfactory
---------------------	-----------------------

Comment	
The framers need to do a better job with housekeeping, there were several board lying around the job site with nails protruding out of them.	

Demolition	N/A
-------------------	------------

Silica Control	Satisfactory
-----------------------	---------------------

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------

Electrical Safety	N/A
--------------------------	------------

Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A