

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Woodside Homes: Arizona

**PROJECT:**  
Legends at Thunderbird



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** SEAN NELSON

**DATE :** MAY 30, 2024

**CITY :**

**STATE :**

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

52 Items Inspected	29 Satisfactory	9 Unsatisfactory	14 N/A
-----------------------	--------------------	---------------------	-----------

The safety checklist hasn't been filled out for May. The fire extinguisher has not been inspected in May. Had to speak to the Framers about their personal protective equipment and electrical safety.

# INSPECTION ITEMS

## Documentation


Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory

## Daily Inspections

**Unsatisfactory**

### Comment

Safety checklist has not been filled out for May.



## Tailgate Meetings

Satisfactory

## Sub-Contractor Meetings


Satisfactory

OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory

### Emergency Items

Access / Egress	Satisfactory
-----------------	--------------

Fire Extinguisher(s)	Unsatisfactory
----------------------	----------------

Comment	
The fire extinguisher was not inspected in May.	

First Aid Kit(s)	Satisfactory
------------------	--------------

Eye Wash Station	Satisfactory
------------------	--------------

Other Fire Fighting Equipment (If needed)	N/A
---	-----

### General Items

Restrooms	Satisfactory
-----------	--------------

Hand Washing Stations	Unsatisfactory
-----------------------	----------------

Comment	
No hand washing station has yet been setup for this job site	-

Waste Containers	Satisfactory
------------------	--------------

Potable Water	Satisfactory
---------------	--------------

Shade	Satisfactory
-------	--------------

## Tools & Equipment

Power Tools	Satisfactory
-------------	--------------

Hand Tools	Satisfactory
------------	--------------

Powder Actuated Tools	N/A
-----------------------	-----

Pneumatic Nailers	Satisfactory
-------------------	--------------

Mobile Elevated Work Platforms (MEWP's)	N/A
---	-----

Powered Industrial Trucks	N/A
---------------------------	-----

Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
---	--------------

Cranes	N/A
--------	-----

Cylinder Storage	N/A
------------------	-----

Ladders	Unsatisfactory
---------	----------------

**Comment**

We found a Framer standing on one of the top steps of an A-frame ladder.



## Operations

### Personal Protective Equipment

**Unsatisfactory**

#### Comment

The Framers were wearing their harnesses, but they were not tied off.



### Trenching & Excavation

N/A

### Fall Protection

**Unsatisfactory**

#### Comment

Framers weren't tied off.

-

### Guardrails

**Satisfactory**

### Floor / Wall Openings

**Satisfactory**

### Supported Scaffolding

N/A

### Mobile Scaffolding


**Unsatisfactory**

#### Comment

We found a rolling scaffold being used with one the wheel brakes broken.



<b>Suspended Scaffolding</b>	<b>Unsatisfactory</b>
------------------------------	-----------------------

Comment	
Need to make sure that scaffolding is green tagged before use.	

<b>Confined Spaces</b>	<b>N/A</b>
------------------------	------------

<b>Impalement Hazards</b>	<b>Satisfactory</b>
---------------------------	---------------------

<b>Traffic Control</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Roofing Operations</b>	<b>Satisfactory</b>
---------------------------	---------------------

<b>Housekeeping</b>	<b>Satisfactory</b>
---------------------	---------------------

<b>Demolition</b>	<b>N/A</b>
-------------------	------------

<b>Silica Control</b>	<b>Satisfactory</b>
-----------------------	---------------------

<b>Rigging Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Hot Work</b>	<b>N/A</b>
-----------------	------------

<b>Electrical Safety</b>	<b>Unsatisfactory</b>
--------------------------	-----------------------

Comment

The Framers were using a severally frayed cord on site.



**Lockout / Tagout** **N/A**

**Stairways, Ramps, Runways** **Satisfactory**

**Other Items (that were observed)** **N/A**