



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Woodside Homes: Arizona	<b>Type of Inspection:</b>	Log a Safety Observation
<b>Project</b>	Legends at Thunderbird	<b>Date of Inspection</b>	July 08, 2024
<b>Inspector Name</b>	Lina Sanchez	<b>Time of Inspection</b>	02:09 PM

## NOTES

7 Items Inspected	6 Satisfactory	1 Unsatisfactory	0 N/A
----------------------	-------------------	---------------------	----------

## INSPECTION ITEMS

### General

Ladder Safety - Log a Safety Observation	Satisfactory
Fall Protection - Log a Safety Observation	Satisfactory
Scaffolding - Log a Safety Observation	Satisfactory
Equipment - Log a Safety Observation	Satisfactory
COVID Protocols / Social Distancing - Log a Safety Observation	Satisfactory
PPE/Hard Hats - Log a Safety Observation	Unsatisfactory
<b>Comment</b>	
no hard hats hvac lot 164	-
<b>OTHER - Click Satisfactory to log a good safety observation, or click unsatisfactory to log a negative safety observation.</b>	Satisfactory