

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Woodside Homes: Arizona	Type of Inspection:	Log a Safety Observation
Project	legends at Thunderbird	Date of Inspection	July 16, 2024
Inspector Name	Lina Sanchez	Time of Inspection	02:34 PM

NOTES						
7	6	1	0			
Items Inspected	Satisfactory	Unsatisfactory	N/A			

INSPECTION ITEMS

General	
Ladder Safety - Log a Safety Observation	Satisfactory
Fall Protection - Log a Safety Observation	Satisfactory
Scaffolding - Log a Safety Observation	Satisfactory
Equipment - Log a Safety Observation	Satisfactory
COVID Protocols / Social Distancing - Log a Safety Observation	Satisfactory
PPE/Hard Hats - Log a Safety Observation	Unsatisfactory
Comment	
lowvolt guy no hard hat 133	-

OTHER - Click Satisfactory to log a good safety observation, or click unsatisfactory to log a negative safety observation. Satisfactory