



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Woodside Homes: Arizona	<b>Type of Inspection:</b>	Log a Safety Observation
<b>Project</b>	legends at Thunderbird	<b>Date of Inspection</b>	August 05, 2024
<b>Inspector Name</b>	Lina Sanchez	<b>Time of Inspection</b>	04:28 PM

## NOTES

7 Items Inspected	5 Satisfactory	2 Unsatisfactory	0 N/A
----------------------	-------------------	---------------------	----------

## INSPECTION ITEMS

General	
<b>Ladder Safety - Log a Safety Observation</b>	<b>Unsatisfactory</b>
<b>Comment</b>	
roofers at 170 ladder not tied off	-
<b>Fall Protection - Log a Safety Observation</b>	<b>Unsatisfactory</b>
<b>Comment</b>	
roofers not tied off 170	-
<b>Scaffolding - Log a Safety Observation</b>	<b>Satisfactory</b>
<b>Equipment - Log a Safety Observation</b>	<b>Satisfactory</b>
<b>COVID Protocols / Social Distancing - Log a Safety Observation</b>	<b>Satisfactory</b>
<b>PPE/Hard Hats - Log a Safety Observation</b>	<b>Satisfactory</b>
<b>OTHER - Click Satisfactory to log a good safety observation, or click unsatisfactory to log a negative safety observation.</b>	<b>Satisfactory</b>