

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Woodside Homes: Arizona

**PROJECT:**  
Palo Verde at North Creek



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** SEAN NELSON  
**DATE :** JULY 25, 2024  
**CITY :**  
**STATE :**

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>29</b> Satisfactory	<b>4</b> Unsatisfactory	<b>20</b> N/A
------------------------------	---------------------------	----------------------------	------------------

The safety center is not yet complete, still a work in progress.

There were a few workers on site not dressed properly.

Also had issues with workers not wearing their hard hats.

# INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Daily Inspections</b>	<b>N/A</b>
<b>Comment</b>	
Safety center in progress.	-
<b>Tailgate Meetings</b>	<b>Satisfactory</b>
<b>Sub-Contractor Meetings</b>	<b>Satisfactory</b>
<b>OSHA Permits</b>	<b>Satisfactory</b>
<b>Labor Law Postings</b>	<b>Satisfactory</b>

<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
-----------------------------------	---------------------

<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>
--------------------------------------	---------------------

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>	<b>Unsatisfactory</b>
-----------------------------	-----------------------

<b>Comment</b>	
----------------	--

The fire extinguisher inside of the safety center has not yet been setup.	-
---	---

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Eye Wash Station</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

## General Items

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Hand Washing Stations</b>	<b>Unsatisfactory</b>
------------------------------	-----------------------

<b>Comment</b>	
----------------	--

No hand washing station has yet been setup for this job site	-
--	---

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------


<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Shade</b>	<b>Satisfactory</b>
--------------	---------------------

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
<b>Hand Tools</b>	<b>Satisfactory</b>
<b>Powder Actuated Tools</b>	<b>N/A</b>
<b>Pneumatic Nailers</b>	<b>Satisfactory</b>
<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
<b>Powered Industrial Trucks</b>	<b>N/A</b>
<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
<b>Cranes</b>	<b>N/A</b>
<b>Cylinder Storage</b>	<b>N/A</b>
<b>Ladders</b>	<b>Satisfactory</b>

## Operations

<b>Personal Protective Equipment</b>	<b>Unsatisfactory</b>
<b>Comment</b>	
The drywall contractors were having issues with wearing shirts and hard hats.	


All workers should wear a shirt with a sleeve and some form of canvas shoe.



**Trenching & Excavation** **Satisfactory**

**Comment**

All open trenches were barricaded.



**Fall Protection** **Satisfactory**


**Comment**

Framers were doing a good job with wearing their fall protection.



**Guardrails** **Satisfactory**


**Comment**

<p>All of the two story homes had handrails and guardrails in place.</p>	
--	---

<p><b>Floor / Wall Openings</b></p>	<p><b>N/A</b></p>
-------------------------------------	-------------------

<p><b>Supported Scaffolding</b></p>	<p><b>Unsatisfactory</b></p>
-------------------------------------	------------------------------

<p><b>Comment</b></p>	
-----------------------	--

<p>All sections of scaffolding should have a ladder access and guardrails.</p>	
--	--

<p><b>Mobile Scaffolding</b></p>	<p><b>N/A</b></p>
----------------------------------	-------------------

<p><b>Suspended Scaffolding</b></p>	<p><b>N/A</b></p>
-------------------------------------	-------------------

<p><b>Confined Spaces</b></p>	<p><b>N/A</b></p>
-------------------------------	-------------------

<p><b>Impalement Hazards</b></p>	<p><b>Satisfactory</b></p>
----------------------------------	----------------------------

<p><b>Traffic Control</b></p>	<p><b>Satisfactory</b></p>
-------------------------------	----------------------------

<p><b>Roofing Operations</b></p>	<p><b>N/A</b></p>
----------------------------------	-------------------

<p><b>Housekeeping</b></p>	<p><b>Satisfactory</b></p>
----------------------------	----------------------------

<p><b>Demolition</b></p>	<p><b>N/A</b></p>
--------------------------	-------------------

<b>Silica Control</b>	<b>Satisfactory</b>
<b>Rigging Operations</b>	<b>N/A</b>
<b>Hot Work</b>	<b>N/A</b>
<b>Electrical Safety</b>	<b>Satisfactory</b>
<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Stairways, Ramps, Runways</b>	<b>N/A</b>
<b>Other Items (that were observed)</b>	<b>N/A</b>