SAFETY INSPECTION REPORT

CONDUCTED FOR:

Woodside Homes

PROJECT:

Huckleberry



INSPECTION TYPE:

General Construction

INSPECTOR: FRANCISCO ROMERO

DATE: JUNE 16, 2024

CITY: VISALIA

STATE: CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION 53 Items Inspected O Satisfactory O Unsatisfactory N/A

Loto

INSPECTION ITEMS		
Documentation		
Site Contact	N/A	
Safety Program (Including IIPP)	N/A	
Heat Illness Prevention Program	N/A	
Safety Data Sheets	N/A	
Daily Inspections	N/A	
Tailgate Meetings	N/A	
Sub-Contractor Meetings	N/A	
OSHA Permits	N/A	
Labor Law Postings	N/A	
Emergency / Other Postings	N/A	
First Aid / CPR Certification	N/A	
Emergency Items		

Access / Egress	N/A
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	N/A
First Aid Kit(s)	N/A
Eye Wash Station	N/A
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	N/A
Hand Washing Stations	N/A
Waste Contatiners	N/A
Potable Water	N/A
Shade	N/A
Tools & Equipment	
Power Tools	N/A
Hand Tools	N/A
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Plarforms (MEWP's)	N/A

Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	N/A
Operations	
Personal Protective Equipment	N/A
Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	N/A
Traffic Control	N/A
Roofing Operations	N/A

Housekeeping	N/A
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	N/A
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A