

SAFETY INSPECTION REPORT

CONDUCTED FOR:
woodside homes

PROJECT:
Wayfare Station



INSPECTION TYPE:
General Construction

INSPECTOR : MANNY OYARZABAL
DATE : AUGUST 27, 2024
CITY : SANTA CLARITA
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	40 Satisfactory	0 Unsatisfactory	13 N/A
------------------------------	---------------------------	----------------------------	------------------

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	Satisfactory

Elevator for Hoisting Workers (if needed)**N/A****Fire Extinguisher(s)****Satisfactory****First Aid Kit(s)****Satisfactory****Eye Wash Station****Satisfactory****Other Fire Fighting Equipment (If needed)****N/A**

General Items

Restrooms**Satisfactory****Hand Washing Stations****Satisfactory****Waste Containers****Satisfactory****Potable Water****Satisfactory****Shade****Satisfactory**


Tools & Equipment

Power Tools**Satisfactory****Hand Tools****Satisfactory****Powder Actuated Tools****Satisfactory****Pneumatic Nailers****Satisfactory****Mobile Elevated Work Platforms (MEWP's)****N/A****Powered Industrial Trucks****Satisfactory**


Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Cranes	N/A
Cylinder Storage	Satisfactory
Ladders	Satisfactory

Operations

Personal Protective Equipment	Satisfactory
Trenching & Excavation	Satisfactory
Fall Protection	Satisfactory
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	Satisfactory

Comment	
Scaffold is fully planked.	

Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A

Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Comment	
Job site is clean and well maintained	
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A