

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Wright Contracting

PROJECT:
Paraduxx Winery



INSPECTION TYPE:
General Construction

INSPECTOR : JORDAN DUZI
DATE : JUNE 14, 2024
CITY : NAPA
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	29 Satisfactory	1 Unsatisfactory	23 N/A
------------------------------	---------------------------	----------------------------	------------------

Site was in good overall condition.

Forms have been installed - all metal stakes were capped.

Heavy equipment not in use was parked out of the way.

Saw guard in place, and cords in good condition.

Workers had PPE in place.

Any hole openings were covered and marked.

Consistently good material storage and housekeeping.

Concrete pour to take place on Tuesday.

2024 Labor Law posters have been hung up in site trailer.


Continue to complete tailgate meetings and daily inspections - file on site.

INSPECTION ITEMS

Documentation

Site Contact	Satisfactory
Comment	
Mick Byrne	-

Safety Program (Including IIPP)	Satisfactory
Comment	
Safety Manual is available on site	-

Heat Illness Prevention Program		Satisfactory
Comment		
Heat Illness Prevention Program is available and site specific information is completed.		-
Safety Data Sheets		Satisfactory
Comment		
Should be available digitally from all active subs		-
Daily Inspections		Satisfactory
Comment		
Continue to ensure daily inspections are being completed and filed on site		-
Tailgate Meetings		Satisfactory
Comment		
Tailgates are being conducted at least every 10 working days		-
Sub-Contractor Meetings		N/A
OSHA Permits		N/A
Labor Law Postings		Satisfactory
Comment		
Labor law postings are in place as required.		
Emergency / Other Postings		Satisfactory
First Aid / CPR Certification		Unsatisfactory

Comment	
CPR cert should be up to date	-

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Comment	
No access issues	-

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Satisfactory
-----------------------------	---------------------

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Eye Wash Station	N/A
-------------------------	------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
------------------	---------------------

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Waste Containers	Satisfactory
-------------------------	---------------------

Potable Water	Satisfactory
----------------------	---------------------

Shade	Satisfactory
--------------	---------------------


Comment	
Shade tents will be needed if temp reaches 80 degrees	-

Tools & Equipment

Power Tools	Satisfactory
--------------------	---------------------

Comment

Saw guard in place



Hand Tools

Satisfactory

Powder Actuated Tools

Satisfactory

Pneumatic Nailers

N/A

Mobile Elevated Work Platforms (MEWP's)

N/A

Comment

No lifts on site

-

Powered Industrial Trucks

N/A

Heavy Mobile Equipment (Excavators, Loaders, etc)

Satisfactory

Comment

Parked out of the way



Cranes

N/A

Comment

Mobile crane on site	
----------------------	---

Cylinder Storage	N/A
-------------------------	------------

Ladders	Satisfactory
----------------	---------------------


Comment	
----------------	--

No ladder violations observed	-
-------------------------------	---

Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------

Comment	
----------------	--

Good PPE observed	
-------------------	---


Trenching & Excavation	Satisfactory
-----------------------------------	---------------------

Fall Protection	N/A
------------------------	------------

Guardrails	N/A
-------------------	------------

Floor / Wall Openings	Satisfactory
------------------------------	---------------------

Comment	
----------------	--

<p>Openings are covered</p>	
-----------------------------	---



<p>Supported Scaffolding</p>	<p>N/A</p>
-------------------------------------	------------

<p>Mobile Scaffolding</p>	<p>N/A</p>
----------------------------------	------------

<p>Suspended Scaffolding</p>	<p>N/A</p>
-------------------------------------	------------

<p>Confined Spaces</p>	<p>N/A</p>
-------------------------------	------------

<p>Impalement Hazards</p>	<p>Satisfactory</p>
----------------------------------	----------------------------

<p>Comment</p>	
<p>All metal stakes are capped</p>	
<p>No issues</p>	

<p>Traffic Control</p>	<p>N/A</p>
-------------------------------	------------

Roofing Operations	N/A
---------------------------	------------

Comment	
----------------	--

See note for Iron workers decking roof	-
--	---

Housekeeping	Satisfactory
---------------------	---------------------

Comment	
----------------	--

Good overall material storage and housekeeping throughout site	-
--	---

Demolition	N/A
-------------------	------------

Silica Control	N/A
-----------------------	------------

Comment	
----------------	--

Hose present and water being used to minimize dust	
--	--

Rigging Operations	N/A
---------------------------	------------

Hot Work	Satisfactory
-----------------	---------------------

Electrical Safety	Satisfactory
--------------------------	---------------------

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	N/A
----------------------------------	------------

Other Items (that were observed)	Satisfactory
---	---------------------