

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Wright Contracting

PROJECT:
San Rafael High School Aquatic Center



INSPECTION TYPE:
General Construction

INSPECTOR: JOSHUA JOHNSON
DATE: FEBRUARY 24, 2025
CITY: SAN RAFAEL
STATE: CA
SITE CONTACT: GC
ADDITIONAL SITE CONTACT: N/A

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

52 Items Inspected	37 Satisfactory	1 Unsatisfactory	14 N/A
------------------------------	---------------------------	----------------------------	------------------

A site inspection was carried out on-site today and I was able to walk the site and look for any safety.

Note the following good items that were observed:

- + Labor laws are posted.
- + Bathrooms are on site.
- + Heavy equipment observed parked safely.

Note the following violations that need to be addressed:

Impalement Hazard

- Rebar on site poses an impalement hazard. Ensure protection is in place. Note: Cal Osha mentions the following: "Protection from Reinforcing Steel and Other Similar Projections. (1) Employees working at grade or at the same surface as exposed protruding reinforcing steel or other similar projections, shall be protected against the hazard of impalement by guarding all exposed ends that extend up to 6 feet above grade or other work surface, with protective covers, or troughs.

Overall, the site was found in satisfactory condition. The team is doing a great job at responding to safety concerns!

ooo Please see additional report notations below. ooo

INSPECTION ITEMS


Documentation	
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory


Comment		-
Ensure these are being done everyday and documented.		-

Tailgate Meetings		Satisfactory
Comment		-
Ensure these are done every 10 days and documented.		-

Sub-Contractor Meetings		Satisfactory
--------------------------------	--	---------------------

OSHA Permits		Satisfactory
---------------------	--	---------------------

Labor Law Postings		Satisfactory
Comment		-
2024 are up. Ensure 2025 are posted.		

Emergency / Other Postings		Satisfactory
Comment		-
Emergency posters are on site and directions to nearest medical facility are posted.		
Comment		-
Log 300A is posted.		-

First Aid / CPR Certification	Satisfactory
--------------------------------------	---------------------

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------


Comment	-
Safe access and egress observed.	-

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Satisfactory
-----------------------------	---------------------

Comment	-
Good job having these in place.	-

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Comment	-
On site.	

Eye Wash Station	Satisfactory
-------------------------	---------------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
------------------	---------------------

Comment	-
Good job having these in place and stocked.	-

Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
Comment	
Provided by the building structure.	-

Tools & Equipment

Power Tools	Satisfactory
Comment	
Guards observed.	-

Hand Tools	Satisfactory
-------------------	---------------------

Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Platforms (MEWP's)	Satisfactory
Comment	
Manuals observed in place.	-



Powered Industrial Trucks	Satisfactory
Comment	
	-

Observed park safely.	-
-----------------------	---

Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
--	---------------------

Comment	-
----------------	---

Parked safely.



Cranes	N/A
---------------	------------

Cylinder Storage	Satisfactory
-------------------------	---------------------

Comment	-
----------------	---

Cylinders are secured

-

Ladders	Satisfactory
----------------	---------------------

Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------

Comment	-
----------------	---

Most workers wearing PPE. Some reminders were given on site.



Trenching & Excavation	Satisfactory
-----------------------------------	---------------------

Comment	
----------------	--

No concerns observed.	-
-----------------------	---

Fall Protection	Satisfactory
------------------------	---------------------

Guardrails	Satisfactory
-------------------	---------------------

Floor / Wall Openings	Satisfactory
------------------------------	---------------------


Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------

Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------


Impalement Hazards	Unsatisfactory
---------------------------	-----------------------

Comment	-
<p>Some areas on site need CAL/OSHA approved protection in place. Other areas were noted as having proper protection in place.</p>	

Traffic Control	Satisfactory
------------------------	---------------------

Roofing Operations	N/A
---------------------------	------------

Housekeeping	Satisfactory
---------------------	---------------------

Comment	
<p>Ensure debris does not build up around the site. This is especially important due to the demolition activities being performed.</p> <p>As seen in the picture, most of the site shows good housekeeping.</p>	-
	

Demolition	Satisfactory
-------------------	---------------------

Silica Control	Satisfactory
-----------------------	---------------------

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------

Electrical Safety	Satisfactory
--------------------------	---------------------

Comment	
No concerns observed.	-

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	Satisfactory
----------------------------------	---------------------

Other Items (that were observed)	N/A
---	------------